



Clevis Pin - This is the only hole I can achieve 1" movement on the pedal before resistance is felt. However, to achieve this, I have to push the arm upwards to a position which is already moving the clutch thrust bearing.