


1909 – 1957

Bulletin Index

(Part 2)

HET Club On-line Library
<http://hetclub.org/burr/lithomepage.htm>

(Effective April 2014)



1909-1919 Bulletins

CL No.	Subject
1	Request for names & addresses of Sub-Agents
2	Advertising pamphlet notification
4	Tire Equipment
5	Generator
6	Gear Ratio
8	Car Order Form
10	Tire Equipment
11	Hudson Car Colors
13	Finish - Upholstering
18	Standard Colors
19	Racing
20	Windshield for Hudson "20"
23	Oil Leakage
25	Body Finish
28	Tire Equipment
29	Extra Equipment Wanted After Car Shipping
31	Notice from Advertising Department
32	Price Increase on Hudson Roadster
33	Equipment of Hudson Roadster at \$1000 Price
36	Clutch Adjustment
37	Transmission Lubrication for Winter Months

Miscellaneous Bulletins (1909, 1910, 1913 & 1940)

(Dec., 23, 1909) Newspaper Article - Hudson and Chalmers Detroit Split
(Jan. 29, 1910) An Important Step in Working Out of the Policy of Hudson
(Feb. 20, 1910) New Types Rear Axle Bearings
(Mar. 5, 1910) Lubrication of Plan Bearing Rear Axle
(Mar. 8th, 1913) Letters to be Sent to Customers
(Mar. 20, 1913) Emphasis Put on Hudson Model "6-54"
Resignation of E. H. Broadwell
Instructions for Attaching Special Front Fender Reinforcement Plates - "54" and "37"
Directions for Securing Gusset Plate to Rear Sill - 7-Pass. Body
1940 Hudson Show Package (Features of 1940 Hudsons)

1909-1913 Sales Department Letters

1909

Dec. 10 - Price Increase of 1910 Hudson Roadster
Dec. 13 - New Hudson Touring Car

1910

Feb. 1 - Selling Points at Exhibits of Hudson Cars
Feb. 18 - Hudson "Twenty"
Mar. 15 - No More Orders for Hudson "37"
Jun. 22 - Additional Roadster

1913

Mar. 14 - Change in Production Policies - Model "37" & Model "54"

1910 Dealer Circular Letters

38 Handling of transmission
40 Windshields
41 Windshield for Touring Car
42 Standard Equip. on Hudson Touring Cars
43 Fisk rims and tires
44 Instructions to salesmen
45 Catalogues

1909-1919 (Cont'd)

1910 Dealer Circular Letters (Cont'd)

- 46 Selden Patent
- 49 Coat Rail on Touring Car
- 51 Specification Requirements for Cars Needed
- 56 Advertising
- 57 7-leaf Touring Car Rear Springs; Power
- 58 Prestolite tank equipment
- 59 Lubrication of Transmission 63 Repair Instructions
- 67 Observance of Licensed Clause in Dealers Contract
- 68 Standard Colors for Hudson Cars
- 70 Hudson Finishes First in Virginia Endurance Run
- 72 Monthly report of cars delivered
- 73 Stromberg Carburetors
- 76 Hudson Dealers and Applicants for 1911 Season
- 80 High speed jumping out in our transmission
- 88 Ad in July 2nd Collier's Weekly magazine
- 92 Note to Hudson Dealers - 1911 Season
- 93 Photograph of every Hudson Dealer wanted
- 96 Note to Hudson Dealers - 1911 Season
- 97 To all Hudson Dealers for 1911

1912-1913 Sales Department Letters

- S-36 Accessory's Available
- S-37 Limousine upholstery samples
- S-38 Standard Colors for 1913 Models
- S-39 Delco Electrical System - Hudson vs Cadillac
- S-44 List Prices on Bodies - Model "37" and "54" S-48 Body Colors
- S-60 Public Demand for Models "54" Torpedo & 7-Pass.
- S-61 Limousine Bodies
- S-68 Trunk Racks - All Models exc. Roadster
- S-69 Orders Discontinue for Model "54" Roadsters
- S-83 Rear Seat Differences between Torpedo and Phaeton
- S-84 Request for Employment letter - R. D. Chapins Chauffer

1912-1913 Service Department Letters

- 170 Front Wheel Roller Bearings - 1910-1911 Models
- 172 Instructions for Repairs - Early Models
- 187 Electric Heaters for Model "54" cars
- 190 Demountable Rim Replacement

1920-1929 Bulletins

1920 Service Department Letters

- Ser. 543/S.E. 34 Adjustment of Carburetor Regulating Sleeve Packing
- Ser. 549 Engine Oiling
- Ser. 550/S.E. 41 Oil Pump Adjustments Ser.
- Ser. 554/S.E. 44 Bearing Service Company Ser.
- Ser. 556/S.E. 47 Claims for Engine Parts Ser.
- Ser. 559/S.E. 49 Charge for Hand Books
- Ser. 560/S.E. 50 Procedures for returning new parts stock to factory

1921 Service Department Letters

- 573/S.E. 60 Deductions on Net Amount of Credit re Claims
- 581/S.E. 66 Cotton Cowl Covers - Returning
- 584/S.E. 67 Paint Specifications - Failure to Specify
- 586/S.E. 69 Oversize Pistons & Rings
- 594/S.E. 73 Orders with Incorrect Symbols & Descriptions
- 595 Part Number Corrections

1921 Service Department Letters (Cont'd)

596/S.E. 78 Claims Sheets
597/S.E. 79 Replacement Parts That Do Not Meet Specifications
599 New Parts List
603/S.E. 86 Essex & Hudson Cylinder Block Regrind
604 New Style Wheels & Rims - Part Numbers
606 New Style Fenders to be used on Earlier Model "0"

1922 Service Department Letters

Ser: 608 (S.E. 88) - Connecting Rod Alignment
Ser: 610 - Hudson Special Shop Tool Prices
Set: 612 (S.E. 93) - Pittsburg Plate Glass Branch Offices
Ser: 613 (S.E. 96) - Letters Pertaining to Service Matters
Ser: 614 (S.E. 97) - E. A. Horn Company Repair Locations
Ser: 615 (S.E. 98) - Hudson & Essex Coach Body Parts List
Ser: 619 - Hudson Model "0" Sedan Parts List
Ser: 620 (S.E. 101) - New Master Parts Catalog for Hudson Super-Six
Ser: 624 (S.E. 103) - Folding Seat Claims
Ser: 625 (S.E. 104) - New Master Parts Catalog
Ser: 626 - New Master Parts Catalog Corrections
Ser: 627 - Radiator Core Replacements
Ser: 628 - New 4-Pass. Phaeton body parts list
Ser: 629 - New 7-Pass. Phaeton body parts list

1929 Hudson & Essex Bulletins (7)

Ser: 1074 - Chassis Lubrication Bulletin (January 21, 1929)
Ser: 1086 - Tuning the Essex Super 6 (February 14, 1929)
Ser: 1090 - Electric Gasoline & Oil Gauge Service (February 28, 1929)
Ser: 1093 - Battery Bulletin (March 5, 1929)
Ser: 1113 - Essex "80" Roadster (April 12, 1929)
Ser: 1118 - Lubrication Instructions (April 18, 1929)
Ser: 1124 - Chase Robes for Hudson & Essex (May 1, 1929)
Ser: 1131 - Distributor Contact & Spark Plug Gap (June 11, 1929)
Ser: 1148 - Controlling Spring Action (July 17, 1929)
Ser: 1186 - Clutch Parts Available (June 22, 1929)

1929 Sales and Parts Bulletins

Ser. 1040 - (January 21) - Hudson & Essex Alemite Fittings
Ser. 1090 - (February 28) - Electric Gasoline & Oil Gauge Service Inst.
Ser. 1093 - (March 5) Battery Service Instruction
March 26 - Sell Service
April 18 - Hudson & Essex Lubrication Instructions
Ser. 1106 - (March 26) Add bolt to Essex car fender
March 26 - Used car sales and stock reports
March 26 - Sales promotion material
June 11 - Spark Plug and Distributor Contact Gaps
July 9 - Sales promotion for local fairs
July 17 - Controlling spring action
July 20 - Dover Finance Plan
July 29 - Service & Maintenance on New Cars
July 31 - (Serial Letter 1164) New List Prices for Numerical Price Lists
August 22 - (Serial Letter 1153) New Prices effective since July 1929
August 22 - (Serial 1185 New Prices July 1929 - Ref. Serial Letter 1153
Sept. 22 - (Serial 1198) Price Changes effect since Aug. 22
Sept. 22 - (Serial 1201 Price Changes effect. since Aug. 2
Nov. 6 - Suggested Group Operation Labor Costs

1930-1939 Bulletins

1930 Hudson & Essex Dealer Service Bulletins

D.S.2003 - Operations & Inspections for Spring (Apr. 30, 1930)
D.S.2006 - Hudson & Essex Gasoline & Oil Level Gauge
D.S.2010 - Rear Axle Lubricant Reduction (Sep. 6, 1930)
D.S. 2011 - Clutch Throwout Bearing Lubrication (Oct. 4, 1930)
1930 - Sept - Gabriel Triple-Hydraulic Shock Absorber Maintenance (Hudson Great 8 - Oct. 18, 1930)
D.S. 2015 - Anti-Freeze & Winter Preparations (Nov. 18, 1930)
D.S. 2016 - Lubrication Rear Axle Gear & Bearings (Nov. 19, 1930)
D.S.2017 - Unloading & Care of New Automobiles (Dec. 4, 1930)
D.S.6036 - Shatterproof Windshield Prices (Dec. 4, 1930)

1931 Hudson & Essex Reference Sheets

Ref. Sheet No. 18 - Hudson & Essex Pistons (Feb. 1931)
Ref. Sheet No. 19 - Hudson & Essex Glass Specs (Feb. 1931)
Ref. Sheet No. 34 - Essex Mechanical Specs. (Dec. 1930)
Ref. Sheet No. 34 - Essex Mechanical Specs. (Jan. 1931)
Ref. Sheet No. 35 - Hudson 8 Mech. Specs. (Dec. 1930)
Ref. Sheet No. 36 - Hudson & Essex Paint Specs. (Jan. 1931)
Ref. Sheet No. 36 - Hudson & Essex Paint Specs. (July 1931)
Ref. Sheet No. 45 - Essex Commercial Mech. Specs. (July 1931)

1931 Hudson & Essex Parts Bulletins

D.S. 6046 - Hudson Valve Springs (Feb. 9, 1931)
D.S. 6049 - Piston Rings BM 35022 - 35024 - 34026 (Mar. 18, 1931)
D.S. 6053 - Piston Pins (Mar. 27, 1931)

1931 Hudson & Essex Service Bulletins

1 Jan. 1931 (D.L.8000) - Service Policy & Delivery Inspection
D.S. 2021 - 1931 Hudson Vibration Dampner (Jan. 27, 1931)
D.S. 2022 - Service on McCord Radiators (Jan. 29, 1931)
D.S. 2024 - Universal Joints (Feb. 23, 1931)
D.S. 2027 - Hudson & Essex Oil Pan (Mar. 16, 1931)
D.S. 2029 - 1931 Essex Exhaust Pipe Bracket (Apr. 21, 1931)
D.S. 2032 - Vapor Lock - (June 18, 1931)
D.S. 2036 - Dealer Service Policy & New Car Insp. (July 1, 1931)
D.S. 2039 - Hudson-Essex 500 & 1500 Mile Inspections D.S2040 - Owner's Service Policy
D.S. 2043 - Carburetor Leaks (Aug. 25, 1931)
Lubrication & Inspection Service (Sep. 13, 1931)

1932 Hudson & Essex Service Bulletins

D.S.2048 - 1932 Lubrication & Mechanical Inspection
D.S.2050 - 1932 Specifications for Licensing Purposes (Jan. 25, 1932)
D.S.2053 - Windshield Rubber Bumper (Jan. 26, 1932)
D.S.2056 - Care of Storage Batteries (Jan. 27, 1932)
D.S.2059 - Lubrication Specifications (Feb. 4, 1932)
D.S.2060 - Transmission Control Lever (Feb. 16, 1932)
D.S.2061 - Hudson Door Striker Plates (Feb. 18, 1932)
D.S.2063 - Lock Cylinders (Mar. 1, 1932)
D.S.2065 - Brake Adjustment (Mar. 2, 1932)
D.S.2066 - Lubrication of Door Hinges (Mar. 2, 1932)
D.S.2070 - Preventing Surface Leakage Battery Positive Terminal
D.S.2071 - AC Spark Plug Tester (Mar. 29, 1932)
D.S.2076 - Radiator Drain Petcocks (Jul. 27, 1932)
D.S.2077 - Bendix Starter Drives (Aug. 10, 1932)
D.S.2078 - Essex Terraplane Service Hints (Aug. 9, 1932)
D.S.2081 - Removal & Application of Tires (Sep. 29, 1932)
D.S.2082 - Terraplane Carb. Heat Control (Oct. 31, 1932)
D.S.2083 - Anti-Freeze Solutions - Aluminum Heads (Dec. 5, 1932)
D.S.2084 - Essex Terraplane Cold Weather Starting

1932 Hudson & Essex Parts Bulletins

D.S.4008 - Accessories (Feb. 10, 1932)
 D.S.401 1 - Philco Transitone Radio (Apr. 25, 1932)
 D.S.4014 - Terraplane Trunk Equipment
 D.S.6084 - Shock Absorber Refill Service Kits (Apr. 12, 1932)
 D.S.6091 - Model K Terraplane Carter Carburetor 243S
 D.S.6099 - Terraplane Hand Starting Device

1932 Hudson & Essex Reference Sheets

1932 Ref. Sheet No. 18 - Hudson & Essex Pistons (Jan. 1932)
 1932 Ref. Sheet No. 34 - Essex Mechanical Specs. (Jan. 1932)
 1932 Ref. Sheet No. 35 - Hudson Mechanical Specs. (Jan. 1932)
 1932 Ref. Sheet No. 36 - Hudson & Essex Paint Specs. (Jan. 1932)
 1932 Ref. Sheet No. 46 - Heat Indicator & Warning Signals (Feb. 1932)
 1932 Ref. Sheet No. 47 - Essex-Terraplane Service Info. (July 1932)

1935 Series Accessory & Parts Merchandising Bulletins

No. 3-A - Accessory Price Changes - Additions & Corrections
 No. 7 - Coach and Sedan Trunks - 1934 & 1935 Cars
 No. 8 - Robes and Pillows
 No. 9 - Door Scuff Plates, Fender Lamps, Vanity Mirrors, Sun Visors, Ash Tray
 No. 11 - Tell-Tale Signal Light
 No. 12 - Startix - 1-4-35
 No. 18 - Electric Clock
 No. 23 - Clock Hanger for Glove Box Door - Install. Clocks in Field
 No. 26 - Wheel Discs
 No. 28 - Fender Lamps
 No. 31 - Kari-Keen Trunk
 No. 40 - Heater Installation

1935 Series Mechanical and Technical Bulletins

No. 2 - Specifications for Licensing Purposes
 No. 4 - Windshield Bumpers #108138
 No. 5 - Carburetor Governor
 No. 6 - Spark Plug Warranty Service
 No. 7 - Electric Hand Service Operations
 No. 12 - Tools Required in Servicing Transmissions

1935 Parts Prices & Specifications

NO.	DATE	SUBJECT
5	1/22/35	Packaged Parts.
7	2/19/35	Brake Lining.
8	5/6/35	Spring Details - Explanation of Car Serial Numbers.
9	3/27/35	Clutch Vacuum Control Cables - Parts Books Corrections.
10	4/3/35	1935 Parts Book Revisions - Brakes - Hand Brake - Drag Link - Springs.
10-A	6/7/35	1935 Parts Book Revisions - Battery - Generator - Differential - Drive Shaft - Wheel Bearings - Clutch.
10-B	6/14/35	1935 Parts Book Revisions - Hard Brake - Frame - Throttle Control - Radiator - Coil - Switches
10-C	7/2/35	1935 Parts Book Revisions - Carburetor and Fuel Pump - Clutch Vacuum Control - Wiring - Generator.
10-E	7/30/35	Parts Book Revisions - Manifold Gaskets - Springs - Battery - Radio Antenna.
10-F	7/30 /35	Parts Book Revisions - Springs - Frame - Coil - Radio and Antenna.
11	4/4/35	1935 Parts Price List.
12	4/18/35	Parts Price Changes.
13	5/1/35	Painted Parts - Terraplane Special Coach Passenger Seat - Parts Book Corrections.
14	5/27/35	Parts Price Changes
15	6/7/35	Confidential Net Price List - 1935 Body Parts Book.
16	6/10/35	Parts Price Changes.
17	6/17/35	Wheel Hubs and Drums - Stabilizer Kit - Drive Gear and Pinion Substitution Discontinued.

1935 Parts Prices & Specification Bulletins (Cont'd)

18	6/20/35	Parts Price Changes.
19	7/ 2/35	Locks - Corrections to Parts Books.
20	8/19/35	Parts Price Changes.
21	8/25/35	Windshield Cleaner - Parts Book Corrections - Special Clutch.
22	8/23/35	New Wire Code Words24
24	11/11/35	Index of 1935 Series Parts Prices and Specifications

1935 Reference Sheets

- No. 2 - Radio Kit for 1935 Models
- No. 4 - Electric Vacuum Horn
- No. 5 - 1935 Duo-Servo Brakes
- No. 6 - Vacuum Clutch Control
- No. 7 - Correct Irregular Tire Wear

1936 Dealer Serial Letters

- No. 12 - Selling Maintenance on the Floor
- No. 16 - Selling Maintenance on the Floor (Cont'd)
- No. 17 - Letters for Owner Follow-up
- No. 34 - Pride In Our Dealer Organization
- No. 35 - Plus Profits

1936 Series General Accessory Policies & Information Bulletins

No. 3 1936 Accessory Program	No. 27 Hudson Upholstery Cleaner
No. 4 Merchandising Accessory Procedures	No. 28 Safety Swinging Stop Light
No. 6 Announcing 1936 Radio Program	No. 29 Seat Covers
No. 7 Heater Thermostats	No. 30 Cowl Ventilator Screens
No. 8 Hudson Hydraulic Brake Fluid	No. 31 Hudson High Gloss Wax
No. 9 Winter Accessories	No. 32 Gas Tank Locking Cap
No. 10 Trunk Kits for 1936 Cars	No. 33 Radiator Insect Screens
No. 13 1936 Accessory Catalogs	No. 34 Sell Heaters Now
No. 14 Wheel Moldings & Terraplane Emblems	No. 35 Price Change - Shock Absorber Fluid
No. 15 Ash Trays for Front Compartment	No. 36 Hudson Lorraine Driving Ligh
No. 16 Heaters - All-Year Accessory Item	No. 37 Heater Program for 1936-1937 Season
No. 17 Windshield Warmer	No. 38 Heater Packages, Knockout Plugs
No. 18 Radio Sales	No. 40 Radiator Cleaner and Inhibitor - New, Improved Packages
No. 19 Accessory Display Board	1936 Bulletin Index (to 7/8/1936)
No. 20 Match Radiator Grille Cover to Cars	No. 41 Radio Sales during August & September
No. 21 New Part Numbers for Canned Material	No. 42 Don't Let Up On Accessory Selling
No. 22 Seat Covers	No. 43 Let's Put a Kick Behind Radio Merchandising
No. 23 Hudson Hydraulic Brake Fluid	No. 47 1936 Windshield Defroster Attachments
No. 24 License Plate Frames	No. 48 Fire Away the Doldrums
No. 25 Arm Rests	No. 50 Winter Accessories
No. 26 Design Change of Water Temp Gauge	

1937 Series General Accessory Policies & Info. Bulletins

- No. 1 - 1937 Accessory Program
- No. 3 - Installation of 1937 Defrosters
- No. 4 - New Windshield Wiper Blades & Accessory Price List
- No. 7 - Fender Lamps
- No. 8 - Temporary Defroster Shortage
- No. 11 - Safety Swinging Stop Light Mounting Bracket
- No. 12 - Heaters - An All-Year Accessory Item
- No. 13 - Change in Accessory Price List

1936 Series General Parts Policies & Info. Bulletins

- | | |
|---|---|
| No. 1 - General Parts Policies & Practicesa) Selected Parts Price List for Independent Garages -Nov. 15, 1935 | No. 17 - 1934-1935 Service Water Pump Parts List No .Auto Lite Parts List |
| No. 2 - Publications Available for 1936 Models | No. 19 - Intake Manifold Drip Part and Corrections |
| No. 3 - Policy Covering Freight & Handling Charges | No. 20 - Numerical Parts Price Supplement |
| No. 4 - Seasonable Winter Items - Radiator Hose, etc | No. 21 - Withdrawal Prepaid Freight \$150 F Parts Ship |
| No. 5 - Electric Hand Parts ListNo. 6 - Service Parts Prices | No. 22 - Un-coded Lock Cylinders |
| No. 7 - Special Price on Transmissions | No. 23 - Steering Gear Bushing & Numerical Parts Price Corrections |
| No. 8 - Heavy Duty Stabilizer | No. 24 - Special Price on Transmissions |
| No. 9 - Service Repair Parts for Shock Absorbers | No. 25 - Prices on Paint & New Dealer Net Prices |
| No. 9 - (Revised) - Service Repair Parts for Shock Absorbers | No. 26 - Special Size Pistons and Rings |
| No. 10 - Running Board Scuff Strips | No. 27 - Service Parts Prices |
| No. 11 - Confidential Net Price List and Hose Lengths
a) Hudson-Terraplane-Essex Dealer Confidential Net Price Lit | No. 28 - Special Prices on Transmissions Revised |
| No. 12 - 1936 Springs and Heater Parts | No. 30 - New Grease Fitting for Steering Spindle Pivot |
| No. 13 - Correction to Selected Parts Price List | No. 31 - Service Parts Price Changes |
| No. 14 - Telegraph Codes | No. 31-A - New Service Parts Prices |
| No. 15 - Carter Carburetor Parts List | No. 32 - Electric Hand Revision |
| No. 16 - E. A. Horn Parts | No. 33 - Tie Rod End Kits |
| | No. 36-B - 1936 Parts Book Revisions & Additions |
| | INDEX - 1936 General Parts Policies & Info. Bulletins |

1936 General Service Policies

- No. 2 - Stabilizer Policy to be Withdrawn
- No. 3 - Supplement & Policy
- No. 4 - Special Warranty Certificates for Goodyear Tires
- No. 7 - Withdrawal of 1935 Electric Hand Policy
- No. 8 - Withdrawal of Transmission Gear Policy
- No. 9 - Withdrawal of Piston Exchange Policy
- No. 10 - Stabilizers on cars 100% from Production
- No. 11 - Classifying Stabilizer Transactions on Claim Certificates
- No. 13 - Reminding You of the Policies Which Will Be Withdrawn
- No. 14 - General Service Policies Manuals Exhausted
- No. 15 - Tourist Policy

1936 General Technical Policies and Info. Bulletins

- No. 2 - Product Performance Report
- No. 3 - Hydraulic Brake Fluid
- No. 5 - 1936 Specifications for Licensing Purposes
- No. 6 - Puncture Proof Tires
- No. 7 - Front End Adjustment Information
- No. 8 - 1936 Specs. for Licensing Purposes
- No. 9 - Flooded Manifolds
- No. 10 - Puncture Proof Inner Tubes
- No. 11 - Installation of Stabilizer Kits & Bars

1936-1937 Accessory Bulletins

- Hudson Tourite Camping Equipment
- Approved Accesories Display Cabinets
- Permanent Service Merchandising
- Ash Trays
- Water Temperature Gauge for DeLuxe Models
- Perfect Seal Gasket Paste

1937 Dealer Service Letters

- No. 12 - Selling Maintenance on the Floor
- No. 16 - Selling Maintenance on the Floor (Cont'd)
- No. 17 - Letters For Owner Follow Up
- No. 24 - Pride In Our Dealer Organization
- No. 35 - Plus Profits

1937 Series General Accessory Policies & Information Bulletins

- | | |
|--|--|
| No. 1 - 1937 Accessory Program | No. 15 - Automobile Thermometer |
| No. 3 - Installation of 1937 Defrosters | No. 17 - Arm Rests for 1937 Cars |
| No. 4 - New Windshield Wiper Blades & Accessory Price List | No. 18 - Auxiliary Seat for Convertible Coupe |
| No. 7 - Fender Lamps | No. 19 - Extra Gross Profit on Sales |
| No. 8 - Temporary Defroster Shortage | No. 21 - Glare Shields and Seat Covers - Prices |
| No. 11 - Safety Swinging Stop Light Mounting Bracket | No. 22 - Hill Hold as an Accessory |
| No. 12 - Heaters - An All-Year Accessory Item | No. 29 - Clock Price List |
| No. 13 - Change in Accessory Price List | No. 32 - New Size Display Box - Initial Sets |
| | No. 33 - DeLuxe or Standard Heaters & Thermometer Price Change |

1937 Series General Parts Policies & Info. Bulletins

- No. 3 - Hydraulic Hill-Hold
- No. 6 - New Frames, Rear Springs, etc
- No. 15 - Master Body Group Parts Book

1937 Series General Technical Policies & Info. Bulletins

- No. 1 - 1937 Specs. for Licensing Purposes
- No. 2 - Winter Servicing
- No. 3 - Generator Output Regulation
- No. 4 - New Way to Drive - 1-11-37
- No. 5 - Electric Hand Service
- No. 6 - Complete Licensing Data
- No. 7 - New Wall Charts
- No. 8 - Mechanical Procedure Manual Inserts

1938 General Technical Policies & Info. Bulletins

- No. 1 - Registration & Licensing Data - 1938 Passenger Cars
- No. 2 - Pre-delivery 500 and 1500 Mile Inspection Cards
- No. 3 - Mechanical Procedure Manual Supplements
- No. 4 - Car Loading Charge, High Output Generator, Loose Fan Belts
- No. 6 - Preparing the Hudson 112 for Demonstrating Use
- No. 8 - Engine Oils

1938-1939 Series General Accessory Policies & Information Bulletins

1938

- No. 1 - 1938 Radio Program
- No. 28 - New Dials - Radios and Clocks No. 1 - 1938 Radio Program

1939

- No. 2 - Suggested Accessory Groups - Car Lines
- No. 3 - New Group for Junior Accessory Display Board
- No. 4 - 1939 Accessory Catalog & Price Lists
- No. 6 - Radiator Grille Covers
- No. 7 - Door Kick Plate Kits
- No. 45 - Fresh Heated Air for Winter Comfort

1939 General Parts Policies & Info. Bulletins

- No. 4-A - Revisions to 1939 Preliminary Parts Book; New Type Differential on Hudson 112
- No. 5 - Service Tappets 1934 thru 1939; Water Pump Service Kits 1936-1937-1938, 1937-1938; Roof Panels
- No. 7 - New Type Brake Linings Models 95 and 97; 1939 Service Transmission Assy.
- No. 12 - New Piston Rings; 1937 Hudson Radiator Ornament Crest; Color Identification Symbol Stamped on New Cars

1939 General Technical Policies & Information Bulletins

- No. 1 - Car Weights & Licensing Data
- No. 10 - New Design Door Latches

1940-1947 Bulletins

1940 General Parts Policies & Info. Bulletins

No. 21 - Special Spring Maintenance Order Pad; Essential Fast Moving Parts

1941 Series General Technical Policies & Info. Bulletins

No. 5 - Rear Lateral Stabilizer Adjust. - Noise Due to Interference

1942 General Parts Policies & Info. Bulletins

No. 1 - Group Parts Book Revision Sheet
No. 3 - Prices on Body Lacquer
No. 6 - Parts Specification Material for 1942
No. 7 - Garage Parts List No. 25
No. 9 - Stock of Catalog Racks Is Exhausted
No. 10 - 1942 Numerical Parts List Prices
No. 12 - Polished Steel Replacement Mouldings

1942 General Accessory Policies and Information Bulletins

No. 1 - Price Changes, Weathermaster
No. 2 - Price Changes, Vacumatic Drive Kit
No. 4 - 1942 Radios in 1941 Cars
No. 8 - Price Changes, HA-204800 Radio Kit
No. 11 - Thermostat Regulator for all Cars Without By-Pass
No. 12 - Radiator Grille Covers for 1940, 1941 and 1942 Car
No. 13 - Venitian Sun Shades Again Available
No. 15 - Resale Schedules - Sleeper Kit Price Changes
No. 16 - Windshield Washer Anti-freeze

1942 General Technical Policies & Info. Bulletins

No. 2 - Car Weights and Licensing Data - 1942 Models
No. 3 - Engine Tune-up
No. 5 - Revised Weights and Licensing Data - 1942 Models
No. 7 - 1942 Radio Adjustments and Installation
No. 8 - Antenna Trimming
No. 9 - Revised Weights and Licensing Data - 1942 Models
No. 10 - Lubricants Affecting Shifting
No. 13 - Tool Price Changes
DL-42-4 - Tire Sizes and Substitutes

1942-1944 - Bulletin Service for Service Station Agreement Holders

1942

No. 33 - Limitation Order L-158, War Production Board

1943

No.. 70 - Substitutions Being Used by Distributors

1944

No.. 76 - 1932-1942 Hudson Brake Cables - Bulletin, Service
No.. 77 - Ring Kits, J-8 Plugs, Heater Hose, De Luxe Seat Covers
No.. 79 - Hudson Weather-Masters; Check Hose

1943 General Parts Policies & Info. Bulletins

No. 18 - Repair 158806 Assembly Instead of Replacing
No. 19 - Additional Functional Parts Groups
No. 20 - Chassis Frames Available at Factory
No. 21 - Parts Supplied for 1940 Transmission Cover Assy.
No. 24 - Flanges Omitted from Exhaust Pipe Assemblies
No. 25 - Substitutions Being Used by Distributors
No. 26 - New Piston Ring Kits

1943 General Parts Policies & Info. Bulletins (Cont'd)

- No. 28 - Clock Dial 204104 Now Available
- No. 29 - BO 201134 Floor Mat Available
- No. 30 - Seat Covers in Stock At Factory
- No. 31 - Brake Cable Identification
- No. 32 - Component Parts for Steel Segment Rings
- No. 34 - Substitution for 162594 Overdrive Throttle Switch
- No. 35 - Brake Hose Troubles Caused by Improper Fluid

1944 General Parts Policies & Info. Bulletins

- No. 26 - New Piston Ring Kits
- No. 28 - Clock Dial 204104 Now Available
- No. 29 - BO 201134 Floor Mat Available
- No. 30 - Seat Covers in Stock At Factory
- No. 31 - Brake Cable Identification
- No. 32 - Component Parts for Steel Segment Rings
- No. 34 - Substitution for 162594 Overdrive Throttle Switch
- No. 35 - Brake Hose Troubles Caused by Improper Fluid

1945 General Parts Policies & Info. Bulletins

- No. 37 - Large Hub Caps for 15" Wheel Discontinued
- No. 39 - Temporary Substitute for 162163 Timing Gear
- No. 41 - Substitute for 1939 Running Boards
- No. 44 - First Type Front Suspension Assemblies Discontinued

1946 Car Distribution Department Bulletins

- DL-1 - 1946 Car Prices
- DL-2 - 1946 Shipping Weights
- DL-7 - Car Prices - 1946 Models - Revised - 4-8-46
- DL-8 - Shipping Weights - Model 51 Cony. & 8-Cyl. Models
- DL-9 - 1946 Prices Commercial Cars
- DL-19 - 1946 Car Prices - Revised 11-22-46

1946 Commercial Car Distribution Department Bulletins

- CD-35 - Car Prices 1946 Model Commercial Car (10-3-46)

1946 General Technical Policies & Info. Bulletins

- No. 7** - Electric Fuel Pump
- No. 11 - Engine Misfiring or Bucking
- No. 17 - Brake Cable Interference
- No. 19 - Special Tool Price Changes

1947 Car Distribution Department Bulletins

- DL-22 - 1946-1947 Car Prices and Models
- DL-23 - 1946-1947 Car Prices & Models - Revised
- DL-24 - Shipping Weights 1946 & 1947 Models - Revised
- DL-25 - Aluminum Cylinder Head - 8 Cylinder Models
- DL-27 - New Green Colors
- DL-28 - Caravan Top for Cab Pickup
- DL-29 - New Color Options
- DL-22 - 1946-1947 Car Prices and Models
- DL-23 - 1946-1947 Car Prices & Models - Revised
- DL-24 - Shipping Weights 1946 & 1947 Models - Revised

1947 Car Distribution Department Bulletins (Cont'd)

DL-25 - Aluminum Cylinder Head - 8 Cylinder Models
DL-27 - New Green Colors
DL-28 - Caravan Top for Cab Pickup
DL-29 - New Color Options
DL-30 - Current Prices & Options - 1947 Models
DL-31 - Front Bumpers for Model 178 - Option Z
DL-33 - Prices of Cars & Options - 1947 Models
DL-35 - New Prices Convertibles & Cab Pickups
DL-37 - White Side Wall Tires
DL-38 - Correction to Bulletin DL-37
DL-39 - New Blue Colors
DL-41 - White Sidewall Tires
DL-42 - Prices of Cars & Options - 1947 Models, Rev.

1947 General Technical Policies & Info. Bulletins

No. 1 - 1947 Model & Series Designation
No. 2 - Sheet Metal Damage
No. 3 - Aluminum Cylinder Heads
No. 4 - Drive-Master Service Inspection Cards
No. 5 - Change in New Car Inspections
No. 6 - Surplus Hydraulic Fluid Caution
No. 7 - Aluminum Head Service Procedure
No. 8 - Shorted Battery Cables
No. 9 - Brake Inspection and Adjustment
No. 10 - New Tool Manual
No. 11 - New Flat Rate Manual
No. 12 - New Equipment Manual
No. 14 - New Mechanical Procedure Manual

1948-1954 Bulletins

1948 Series Car Distribution Department Bulletins

DL.48-1 - Prices of Cars & Options - 480 Series
DL.48-2 - Airfoam Seat Back Cushion - Front Seat Only, Commodore
DL.48-3 - Shipping Weights, 482 & 484 Sedans
DL.48-5 - Shipping Weights - 3-16-48
DL.48-6 - New Tan & Bronze Colors
DL.48-6A - Correction in Effective Date New Tan & Bronze Colors
DL.48-7 - Optional Equipment
DL.48-8 - Revised Leather Trim Prices
DL.48-10 - Shipping Weights - 5-25-48
DL.48-11 - New Gray Colors
DL.48-12 - Weather Control Equip. with Ranco Heat Control
DL.48-13 - New Blue Colors
DL.48-14 - Change in Interior on Super Models
DL.48-15 - Leather Trim Prices, 481 Business Coupe - Correction to Bulletin
DL.48-13 - (New Blue Colors)
DL.48-16 - New Prices 480 Series - 6-16-48
DL.48-17 - New Prices, Optional Equip. - 6-28-48
DL.48-18 - Satin Finish on Instrument Panel
DL.48-20 - New Tire Option Prices
DL.48-21 - List Prices, Convertibles - 7-26-48
DL.48-22 - New Prices 480 Series - 9-1-48
DL.48-23 - Correction to Bulletin DL.48.26
DL.48-24 - Federal Excise Tax Refunds - 9-17-48
DL.48-25 - End 480 Production, Start 490 Production Dates

1948 Series General Accessory Policies & Info. Bulletins

No. 1 - Hudson Kleenex Tissue Dispenser	No. 21 - Windshield Washers
No. 2 - New Hudson Seat Covers	No. 22 - HA-166704 - Automatic Battery Filler
No. 3 - Hudson Weather Control	No. 23 - Radios Avail. for the New Hudson
No. 4 - Custom License Plate Frames	No. 24 - Cigar Lighters
No. 5 - Car Washing Sponges	No. 25 - Oval Rear View Mirror
No. 6 - Home Battery Charger	No. 26 - Windshield Cleaner Blades & Arms
No. 7 - Hand Rubbing Compound	No. 27 - Lacquer Thinner - Drum Lots
No. 8 - New Hudson Hydraulic Jack	No. 28 - Installation Inst. - HA-213214 Cigar Lighter
No. 9 - Hudson Gasoline Filter	No. 29 - Hudson Automatic Battery Filler - New Circular Available
No.10 - Glare-Proof Mirror	No. 30 - New Outside Rear View Mirror
No. 11 - Hudson Rust Dissolver	No. 31 - New Spotlights
No. 12 - Hudson Glass Cleaner	No. 32 - Hudson Six Oil Filter
No. 13 - Hudson Now Supplying AC Fuel Pump Parts	No. 33 - Champion Spark Plugs - 5000 Basis Franchise Eliminated
No. 14 - New Accessory Prefix	No. 34 - Thermaster Program
No. 15 - Super Series Seat Covers	No. 35 - Club Coupe Seat Covers
No. 16 - New Hudson Exhaust Deflectors	No. 36 - Owner Supply Kit
No. 17 - Hudsonite Clutch Compound	No. 37 - Hudson Windshield Glass Sealer - HS-214698
No. 18 - New Hudson Batteries	No. 38 - New Automatic Utility Lights
No. 19 - Valve Grinding Compound	No. 39 - Tire Pressure Gauge
No. 20 - Wheel Trim Rings Kit	No. 40 - Radiator Flush, Rust Preventative, Stop Leak
No. 21 - Windshield Washers	No. 41 - New Seat Cover Prices
No. 22 - HA-166704 - Automatic Battery Filler	No. 42 - Window Ventshades Hudson Approved
No. 23 - Radios Avail. for the New Hudson	
No. 20 - Wheel Trim Rings Kit	

1948 Series General Accessory Policies & Info. Bulletins (Cont'd)

- | | |
|---|---|
| No. 43 - Hub Cap Kits - Large | No. 61 - White Sidewall Tire Cleaner |
| No. 44 - Oil Filter Installation Instructions | No. 62 - Vacuumotive Drive Kits |
| No. 45 - Mounting Brackets, Fire Extinguisher Emerg. Unit | No. 63 - Hudsonite Clutch Compound |
| No. 46 - Radiator Grille Guards | No. 64 - Venetian Sun Shades |
| No. 47 - New Hudson Fog Lamp | No. 65 - Hudson Tar & Road Oil Remover |
| No. 48 - Hand Rubbing Compound, Hudsonite, Price Changes | No. 66 - Weather Controls with Thermostat Valves |
| No. 49 - New Battery Prices - 5-4-48 | No. 67 - Front Door Ventilation Wing Shield |
| No. 50 - New Auto-Home Combination Electric Shaver | No. 68 - Radio, Antennas and Weather Control, Price Changes |
| No. 51 - New Hudson Back-up Lamp | No. 69 - AC Fuel Pump and Repair Kits |
| No. 52 - Window Ventshades for Coupes & Broughams | No. 70 - Direction Indicator, Large Hub Cap, Wheel Trim Rings - Price Changes |
| No. 53 - Pocket Moldings - Super Series | No. 71 - Hudson Champion Spark Plugs |
| No. 54 - Windshield Wiper Arms, Blades - Price Revision | No. 72 - Hudson Rear Seat Radio Speaker |
| No. 55 - Direction Indicator Kits Now Available | No. 74 - Replacement Batteries, New Prices |
| No. 56 - Replacement Batteries for all Cars | No. 79 - Headlamp, Pocket Molding Kits - Price Changes |
| No. 57 - HS-210637 - Car Washing Chamois | No. 81 - Cooling System Supplies |
| No. 58 - Rear Window Wipers | No. 82 - Glare-Proof Rear View Mirror, Price Change |
| No. 59 - Liquid Glaze, Lower Prices Pint Size | No. 84 - Polishing Cloth - Customer Christmas Gift |
| No. 60 - Polaroid Day Driving Visor No Longer Supplied | |

1948-1949 Parts Merchandising Bulletins

1948 - 480 Series

- No. 1 - Parts Bin Labels
- No. 2 - Steel Bin Display Units
- No. 3 - Sealed Power Piston Ring Sets, New Prices
- No. 4 - Hudson Touch-Up Lacquer, 1946 thru 1948
- No. 5 - Radiator Pressure Cap, 480 Series
- No. 6 - Hudson Sealed Power Piston Ring Sets, 7-30-48
- No. 7 - Handy Holder
- No. 8 - Rebuilt Skeleton Engines - 6 Cyl., 1936-1947
- No. 9 - Lamp Bulb Price & Prefix Changes
- No. 10 - Pedrick Piston Ring Sets, New Prices

1949 - 490 Series

- No. 1 - Hudson-Pedrick Piston Ring Sets
- No. 2 - Fuse Kit Price & Prefix Changes
- No. 3 - SP-161664 - High Temp. Thermostat - 1948-1949
- No. 4 - Battery Price Change
- No. 5 - Dec. & Jan. Spark Plug Sales Campaign
- No. 6 - Fan Belt Sales Campaign
- No. 7 - 1949 Hudson Paint Program
- No. 8 - New Prices SP-302265 Radiator Pressure Cap
- No. 9 - Hudson Sealed Power Piston Ring Sets
- No. 10 - 2-24-49 - March Brake Campaign No. 10 - 3-17-49-
Reduced Battery Prices
- No. 11 - Rebuilt Engine Part Numbers, Correction

1949 - 490 Series (Cont'd)

- No. 12 - Lamp Bulbs, Cartons of Ten
- No. 13 - Brake Cylinder Repair Kits - 480-490 Series
- No. 14 - New Low Battery Prices
- No. 15 - Factory Rebuilt Basic Engines, Revised
- No. 16 - New Paint Kit
- No. 17 - New, Low, Piston Ring Prices
- No. 18 - New Paint Kit, Correction
- No. 19 - Suggestions on Hudson Touch-up Lacquer
- No. 20 - New Engine Overhaul Gasket Kits
- No. 21 - Carburetor Bargain Sale
- No. 22 - Price Schedule - 490 Series Refinishing Lacquers
- No. 23 - Use of Hypoid Gear Lubricant
- No. 24 - New 490 Series Colors
- No. 25 - Parts Shortage, Vacuumotive Drive,
Drive-master, Overdrive
- No. 26 - Hudsonite Brake Fluid, Shock Absorber Fluid
- No. 27 - Sheet Metal Parts, Adequate Supply
- No. 28 - 490 Series Touch-up Lacquers
- No. 29 - New Color, Bright Red
- No. 30 - 480-490 Series Color Chart
- No. 31 - Gear and Pinion Sets
- No. 32 - Price Reductions - Bulbs, Floor Mats, Windshield Wipers
- No. 33 - Water Pump Repair Kits

1948 Series General Service Policies & Info. Bulletins

- No. 1 (New Series) - New Bulletin series on Replacement Matters
- No. 2 (New Series) - Tourist Owners (Manufacturer's Warranty)
- No. 4 (New Series) - Authorized Service Stations
- No. 5 (1948 Series) - Weather Strip and Panel Kit

1949 General Parts Policies & Info. Bulletins

- 1 - Bulletin No. 5 Withdrawn
- 3 - Hudson Radio Warranty, Installation
- 4 - Revised Sealing Instructions
- 5 - Bulletin Corrections
- 6 - Returning Material and Damaged Parts

1948 General Parts Policies & Info. Bulletins

- No. 2 - Change in Rear Springs Used On 1947 Sed, Club Cpe and CvBro
- No. 3 - Prices on Body Lacquer
- No. 4 - Two New Parts Groups - SP and HS
- No. 5 - New Parts Price Book 463
- No. 6 - Quick Action Catalog Holder
- No. 7 - Auto-Lite Distributor Parts List - 6 Cylinder
- No. 8 - Auto-Lite Distributor Parts List - 8 Cylinder

1948-1953 General Technical Policies & Info. Bulletins

1948 (New) Series

- No. 1 - Special Brake Adjustment on First Cars
- No. 2 - Model Designations
- No. 4 - Product Performance Reports
- No. 5 - Service Specification List
- No. 6 - Door Bottom Weatherstrip Change
- No. 7 - New Car Inspection Cards
- No. 8 - Door Striker Adjustment
- No. 9 - Under Panel Noises
- No. 10 - Additional Data - Dust and Fumes
- No. 11 - Governor Discontinued
- No. 12 - Importance of Pre-Delivery Inspection
- No. 13 - Air Filter Pad Discontinued
- No. 14 - New Heater Control Unit
- No. 15 - Propeller Shaft Vibration
- No. 16 - Exhaust Damper Anti-Rattle Spring Installation
- No. 17 - Engine Oil Loss
- No. 18 - Instruct Owners on Tire Maintenance
- No. 19 - Windshield Glare Reduction
- No. 20 - New Flat Rate Manual
- No. 21 - Drive-Master & Vacu-Motive Drive Instructions
- No. 22 - Radiator Pressure Cap Available
- No. 23 - Cracked Battery Cases
- No. 24 - New Tool Price List
- No. 25 Overdrive Lubricant Level

1949 - 490 Series

- No. 1 New Mechanical Procedure Manual - 490
- No. 3 - Distributor Spark Advance Changed
- No. 4 - Engine Stalling on Grades
- No. 5 - Revised Spark Advance
- No. 6 - Rear Axle Lubricant

- No. 7 - Check Storage Batteries
- No. 8 - Transmission Clearance
- No. 9 - Door Lock Operation
- No. 10 - New Specification & Data List - 480-490 Series
- No. 11 - Flywheel Marking Changed
- No. 12 - Ventilation and Driving
- No. 14 - Rear Compartment Floor Panel Breakage
- No. 15 - New Tool Guide
- No. 16 - Carburetion Change
- No. 17 - Service Merchandiser Announcement
- No. 18 - Complete Kent-Moore Tool Guide - Apr. 1, 1949
- No. 19 - Shorted Ignition
- No. 20 - Fuel Pump Installation
- No. 22 - Air Noise - Heater Tube Redesigned - 480-490 Series

1951 - "A" Series (3)

- Number 11 - Radio Interference
- Number 13 - Radio Speakers Boxed Separately
- Number 14 - Cylinder Head Interchange

1952 - "B" Series

- Number 1 - New Car Appearance (Paint Care)
- Number 2 - Chrome Protection 1952 Models
- Number 3 - Technical Information B Series
- Number 4 - OPS Flat Rate Approval
- Number 6 - Twin-H Carburetor Adjustment 7B Models

1953 - "C" Series

- T-195 - Number 2 - Power Steering Operation
- T-158 - Number 5 - Radio Speakers Installed at Factory

1948-1954 - Service Promotion & Equipment Bulletins

1948

- 1- Uniforms for the Hudson Man
- 3 - Departmental Signs
- 4 - Servi-Cars
- 11 - Departmentized Service Departments
- 12 - Owner Follow-up System
- 14 - Liquid Glaze Appearance Department
- 15- New Service Customers 16 - Budget Plan
- 17 - Direct By Mail Service Cards
- 16 - Service & Sales Bulletin Boards
- 19 - Collier's Direct Market Mail Program
- 20 - Hudson Approved Body and Fender Repair Kit
- 21- Ozone Generating Machine

1949 (Equipment)

- No. 1 - Service Equipment for Hudson Dealers
- No. 2 - GEM Fender & Seat Covers for Hudson Dealers

1949 (Service Promotion)

- No. 1 - Vibromatic Compressed Air Cleaner
- No. 2 - Ozone Generating Machines
- No. 3 - Direct Mail Program

1948-1954 Severe Usage Parts & Price Bulletins

- No. 1 (11-15-52) - Unusually Severe Usage Parts Kit
- No. 4 (3-20-53) - Severe Usage Rear Axle Assembly for 4, 5, 6, & 7 B and C Series and 8B
- No. 6 (3-20-53) - Twin-H Exhaust Manifold for 5B, 6B, 713 and 5C, 7C (S-393)
- No. 9 (5-8-52) - Severe Usage Kit & Special Cylinder Heads (S-275)
- No. 10 (6-16-52) - Twin -H Exhaust Manifold and Pipe Kit
- No. 13 (10-30-52) - New Engine Front Mounting Kit
- No. 12 (6-8-53) - New Camshaft #309742 for 7A, 7B and 7C engines (S-434)

1949 (490 Series) Car Distribution Department Bulletins

- DL.49-1 - Shipping Weights, Convertible Models
- DL.49-2 - Shipping Weights - 490 Series
- DL.49-3 - Prices of Cars and Options - 490 Series
- DL.49-4 - Prices & Options of Cars & Options - 490 Series - Revised
- DL.49-6 - Shipping Weight - 493 Series Brougham
- DL.49-7 - Prices 490 Series Cars - Revised 4-19-49
- DL.49-9 - Tire Equip. - Convertible Models
- DL.49-11 - New Hudson Gem-Lustre Body Finish & Colors
- DL.49-12 - Hudson Gem-Lustre - Correction to Bulletin DL.49-11
- DL.49-13 - Identification of New Paint Colors
- DL.49-14 - New Hudson Gem-Lustre Body Finish & Colors
- DL.49-15 - New Hudson Gem-Lustre Body Finish & Colors
- DL.49-16 - New Hudson Gem-Lustre Body Finish & Colors
- DL.49-17 - Colors No Longer Available
- DL.49-18 - Hudson Gem-Lustre Body Finish & Colors
- DL.49-19 - New Red Body Color

1949 (Service Promotion) Cont'd

- No. 4 - Combination Air Compressor and Battery Charger
- No. 5 - March Brake Campaign
- No. 6 - Ingersoll Rand Electric Impact Tools
- No. 7 - April-May Spring Conditioning Program
- No. 8 - Collier's Preventive Service Mailer for July
- No. 9 - Uniforms for Hudson Dealer's Parts & Service Personnel
- No. 10 - Hudson Aug.-Sep. Liquid Glaze Campaign
- No. 11 - Index Dividers for Service Promotion Material
- No. 12 - Hudson Service of the Month Window Cartoons
- No. 13 - Fall Service Mailing Campaign
- No. 14 - Twin Post Lifts
- No. 15 - Hudson Service of the Month - Oct.-Nov.

1952

- No. 1 - Chrome Protection
- No. 8 - Servi-Car - Customer Car Pickup

1954

- No. 9 - Spring Clean-up, Paint Up

1949 (490 Series) General Accessory Policies & Info. Bulletins

- No. 1 - Auxiliary Floor Mats
- No. 2 - 1946-1947 Seat Covers
- No. 3 - Assist Strap Kit
- No. 4 - Convertible Top Dressing
- No. 5 - Dealer Accessory Price List - 1949 Models
- No. 6 - Fuel Pump Price Changes - 12-30-48
- No. 7 - Custom License Plate Frames
- No. 8 - Free Master Air Gauge
- No. 9 - Thermaster Portable Refrigerator - New Prices
- No. 10 - Accessory Lamp Display Stand
- No. 11 - Cooling System Cleaner
- No. 12 - Hudson Anti-Freeze
- No. 13 - Hudson Hurricane Auto Shampoo
- No. 14 - New Hudson Oil Filters by Fram
- No. 15 - Thermaster and Woodland Folding Grille
- No. 16 - Demonstrate Rear Seat Speakers
- No. 17 - Wind & Rain Deflectors
- No. 18 - Oil Filters and Cartridges - Volume Discounts
- No. 20 - Direction Indicators - Fits All Cars
- No. 21 - Radiator Grille Guard Kits - Component Parts
- No. 22 - Karvisor - Component Parts
- No. 23 - Price reductions
- No. 24 - Window Ventshades - Price Reduction (6-30-49)
- No. 25 - Hudson Lock-Ease
- No. 26 - Shop & Owner Supplies - New, low, dealer nets
- No. 27 - Plastic Seat Cover Program Cancelled
- No. 28 - Karvisor Display Rack
- No. 30 - How to Clean Hudson Seat Covers
- No. 31 - Windshield Washer - Price Reductions - 7-20-49
- No. 32 - Fuel Pump Assy - New Prices (7-25-49)

1949 (490 Series) General Parts Policies & Info. Bulletins

- No. 1 - Price Changes & Color Options
- No. 2 - Price Changes, Service Replacement Parts
- No. 3 - Price Changes, Service Replacement Parts - 1-15-48
- No. 4 - List & Net Prices on Special Net Items
- No. 5 - New Numerical Price Supplement #464
- No. 6 - List & Net Price Changes, Special Net Items
- No. 7 - New Dealer Net Price List - 1-17-49
- No. 13 - List & Net Price Changes, Special Net Items - 5-18-49 No.
- 14 - New Rear View Mirror Support
- No. 16 - Bearing Inserts, Front & Rear Bumper Bars
- No. 17 - Handy Shift Connectors Changed
- No. 18 - List & Net Price Changes, Special Net Items - 9-15-49
- No. 19 - List & Net Price Changes, Special Net Items - 9-16-49
- No. 20 - New Numerical Price List Supplement #465
- No. 21 - List & Net Price Changes, Special Net Items - 10-31-49
- No. 22 - List & Net Price Changes, Special Net Items - 11-3-49
- No. 23 - List & Net Price Changes, Special Net Items - 11-22-49

1949 - General Service Policies & Info. Bulletins

- 1 3-22-49 Bulletin No. 5 Withdrawn
- 3 4-15-49 Hudson Radio Warranty, Installation
- 4 6-20-49 Revised Sealing Instructions
- 5 7-7-49 Bulletin Corrections
- 6 8-16-49 Returning Material and Damaged Parts

1949 Parts Merchandising Bulletins

No.	Subject	No.	Subject
1.	Pedrick Piston Ring Sets	18.	New Paint Kit - Corrections
2.	Fuse Kit Price & Prefix Change	19.	Suggestions on Hudson Touch-up Lacquer
3.	High Temp Thermostat (SP-161664)	20.	New Engine Overhaul Gasket Kits
5.	Plug Nickle Campaign - Dec. & Jan.	21.	Carburetor Bargain Sale Prices
6.	Sell Fan Belts	22.	490 Series Refinishing Lacquer Prices
7.	1949 Hudson Paint Program	23.	Usage of Hypoid Gear Lubricant
8.	New Prices - SP 302265 Radiator Cap	24.	New 490 Series Colors
9.	Sealed Power Piston Ring Sets - 6 Cyl.	25.	Vacumotive Drive/OD Parts Shortage
10.	March Brake Campaign (2-24-49)	26.	Hudsonite Brake and Shock Absorber Fluid
10.	Reduced Battery Prices (3-17-49)	27.	Adequate Supply - Sheet Metal Parts
11.	Rebuilt Engine Part No. Descriptions	28.	490 Series Touch-Up Lacquers
12.	Lamp Bulb - Cartons of 10 (Prices)	29.	New Color - Bright Red
13.	Brake Cyl. Repair Kits (480-490 Ser.)	30.	480-490 Series Color Chart
14.	New Low Battery Prices	31.	Gear and Pinion Sets Now Available
15.	Factory Rebuilt Basic Engines	32.	Price Reductions - Bulbs, Floor Mats
16.	New Paint Kit	33.	Water Pump Kits
17.	New Low Piston Ring Prices		

1949 Parts Merchandising Bulletins

No.	Subject	No.	Subject
1.	Pedrick Piston Ring Sets	18.	New Paint Kit - Corrections
2.	Fuse Kit Price & Prefix Change	19.	Suggestions on Hudson Touch-up Lacquer
3.	High Temp Thermostat (SP-161664)	20.	New Engine Overhaul Gasket Kits
5.	Plug Nickle Campaign - Dec. & Jan.	21.	Carburetor Bargain Sale Prices
6.	Sell Fan Belts	22.	490 Series Refinishing Lacquer Prices
7.	1949 Hudson Paint Program	23.	Usage of Hypoid Gear Lubricant
8.	New Prices - SP 302265 Radiator Cap	24.	New 490 Series Colors
9.	Sealed Power Piston Ring Sets - 6 Cyl.	25.	Vacumotive Drive/OD Parts Shortage
10.	March Brake Campaign (2-24-49)	26.	Hudsonite Brake and Shock Absorber Fluid
10.	Reduced Battery Prices (3-17-49)	27.	Adequate Supply - Sheet Metal Parts
11.	Rebuilt Engine Part No. Descriptions	28.	490 Series Touch-Up Lacquers
12.	Lamp Bulb - Cartons of 10 (Prices)	29.	New Color - Bright Red
13.	Brake Cyl. Repair Kits (480-490 Ser.)	30.	480-490 Series Color Chart
14.	New Low Battery Prices	31.	Gear and Pinion Sets Now Available
15.	Factory Rebuilt Basic Engines	32.	Price Reductions - Bulbs, Floor Mats
16.	New Paint Kit	33.	Water Pump Kits
17.	New Low Piston Ring Prices		

1950 (500 Series) Car Distribution Department Bulletins

DL.50-1 - Prices of Car & Options - 500 Series
 DL.50-3 - Weights of Optional Equipment - 500 Series
 DL.50-5 - Car Colors Pacemaker Models
 DL.50-6 - New Prices - Super-Matic Drive, Drive-Master, Overdrive
 DL.50-12 - New Red Body Color

1950-1954 Series General Parts Policies & Information Bulletins

1950

Nr. 7 - New Dealer Material Order
 Nr. 8 - List & Net Prices, Special Net Items - 2-14-50
 Nr. 9 - Windshield Cleaner & Operating Parts
 Nr. 10 - Electric Auto-Lite Distributor Parts List
 Nr. 11 - Electric Auto-Lite Starting Motor Parts List

1950-1954 Series General Parts Policies & Info. Bulletins

1951

- No. 7 - New Dealer Material Order
- No. 8 - List & Net Prices, Special Net Items - 2-14-50
- No. 9 - Windshield Cleaner & Operating Parts
- No. 10 - Electric Auto-Lite Distributor Parts List
- No. 11 - Electric Auto-Lite Starting Motor Parts List

1952

- No. 2 - (S-210) - Roof Panel Substitution

1953

- No. 6 - (S-393) - Twin Exhaust Manifold & Pipe Kit
- No. 7 - (S-515) - Revised Numerical Parts Price List pages
- No. 10 - (S-415) - Numerical Price List Revised Pages

1954

- No. 5 - (S-578) - Twin Carb. Install. Kit - 6D, 7D

1950-1951 General Accessory Policies & Info. Bulletins

1950

- No. 1 - Wheel Trim Rings
- No. 2 - Large Hubcap Kit for Pacemaker

1951

- 2 11-17-50 New Hudson Weather Controls
- 3 11-17-50 Oil Filters and Cartridges
- 5 11-21-50 Accessory Lamp Display Stand

1951 ("A" Series) Car Distribution Department Bulletins

- DL.51-1 - Prices Options A Series - 9-26-50
- DL.51-8 - Large Plastic Rear Window - Convertibles
- DL.51-9 - New 2-Tone Color Combinations
- DL.51-11 - A Series Car and Option Prices
- DL.51-13 - New Colors 1951 Models
- DL.51-14 - Electric Clocks Omitted A Models
- DL.51-18 - Electric Clocks Avail A Models
- DL.51-19 - Shipping Weights - 4-25-51
- DL.51-20 - Hudson Hollywood Models - Prices
- DL.51-25 - Prices of Cars and Options A Series (Rev)
- DL.51-27 - Corinthian Cream Color

1952-1953 General Accessory Policies & Info. Bulletins

1952

- 6 (SA-95) 3-21-52 Permanent Anti-Freeze
- 9 (SP-112) 6- 5-52 Outside Visors - Karvisors
- 10 (SA-119) 6-13-52 Liquid Glaze "Apperance" Kit
- 14 (SA-127) 9- 4-52 New Back-up Light Location

1953

- 6 (SA-140) 12-18-52 New 1953 8 Tube Radio
- 10 (SA-208) 11-30-53 1954 Gasoline Door Guards
- 14 (SA-156) 4-22-53 New Hornet Seat Covers
- 19 (SA-166) 6- 1-53 Ventshades for Jet & Super Jet
- 22 (SA-172) 6-29-53 Wire Wheels Available
- 25 (SA-178) 7-13-53 Jet Electric Clock

1953 "C" Series - Car Distribution Department Bulletins

- DL.53-1 - Prices Options "C" Series
- DL.53-4 - New 8-Tube Radio Price
- DL.53-7 - Shipping Weights Optional Equipment
- DL.53-11 - Prices of Optional Equipment
- DL.53-13 - Change in Option Prices - Wire Wheels
- DL.53-15 - Additional Shipping Weights

1955-1957 AMC-Hudson Bulletins

1955 AMC-Hudson Accessory Merchandising Bulletins (8)

No. 7 - Radio Price Slashed
No. 8 - New Outside Rear View Mirror
No. 9 - 1954 Accessory Prices Cut
No. 10 - 1955 Accessory Price Folder
No. 12 - Bargain Prices - 1955 Rambler Fog Lamps
No. 13 - 1955 Accessory Folder
No. 16 - Hudson Cooling System Chemicals
No. 20 - 1954 Accessory Price Reduction Withdrawn

1955 AMC-Hudson Body Section Bulletins (9)

HZ (HD) 55-4 - Electrically Operated Windows
HZ (HD) 55-5 - Interior Paint Colors - 5500 Series
HZ (HD) 55-7 - Cross Country Travel Rack Hold Down Strap
HZ (HD) 55-8 - Water Leaks 1955 40-60-80 Series
HZ (HD) 55-9 - Door Arm Rest Pads
HZ (HD) 55-10 - Door Armrest Pads - 1955 Series
HZ 55-12 (HD) 55-11 1955 Prelim. Flat Rate Ops - Acc., Fenders, Horn, Instrument Panel, Seats, Speedometer, Trunk Cover
HZ 55-16 (HD) 55-15 - 1955 Prelim. Series Flat Rate Ops. - Engine, Front Suspension, Steering Gear
USHZ 55-1 - USHD 55-1 - Air Dry Repair Enamel - 5500 Series

1955 AMC-Hudson Technical Bulletins (Groups 1.000 thru 13.000)

1955 Group 1.000 - Engine

HZ 55-9 (HD 55-6) - Intake Valve Stem Oil Deflector

1955 Group 3.000 - Electrical-Wiring-Lamps

HZ (HD) 55-5 - Circuit Breakers & Light Switch - Hornet & Wasp
HZ 55-4 - Dir. Signal Switch & Cam - Hornet & Wasp

1955 Group 4.000 - Fuel - Carburetion - Exhaust System

HZ 55-8 - Vapor Lock - V-8 Series (HD 55-7)

1955 Group 5.000 - Clutch

HZ (HD) 55-3 - Wasp Clutch Fabrica Insulator Shim

1955 Group 6.000 - Transmission

HZ 55-9 (HD 55-8) - Rough 2-3 Upshift - Hydramatic

1955 Group 8.000 - Brakes & Wheels - Hub & Drum

HZ 55-5 - Wheel Rim Air Leaks
HZ (HD) 55-7 - Dust Cover Repair Kit - Met. Series

1955 Group 9.000 - Rear Axle - Propeller Shaft

HZ (HD) 55-3 - Rear Axle Pinion Bearing Cup Spacer

1955 Group 10.000 - Front Axle-Front Suspension-Steering Gear

HZ 55-8 - Idler Arm Rattle
HZ 55-9 - Power Steering Cover Leak
HZ 55-10 - Door Armrest Pads
HZ 55-11 - Power Steering Pump Pulley

1956 AMC-Hudson Bulletins

Groups 1.000 thru 13.000

Group 1.000 - Engine

HZ 56-1 - Vibration Damper - 1956 Rambler Series
HZ 56-2 - Timing Cover Oil Seal Leakage - V-8 Series
HZ 56-3 - Engine Rear Support Reinf. - 1956 Rambler Series
HZ 56-4 - Engine Rear Crossmember Brace - 195640 Series
HZ 56-6 - Valve Spring Baffles - 1955-56 80 Series
HZ 56-8 - Rear Main Bearing Torque Specs - 1956 Special V-8 50 Series
HZ 56-9 - Cyl. Head Corrosion & Leakage - 1955-56 Hornet 6 Series

Group 2.000 - Cooling System

HZ 56-1 - Water Pump Cartridge Lube. - 35610 Series

Group 3.000 - Electrical - Wiring - Lamps

HZ 56-1 - Ignition Timing - 1956 Rambler Series
HZ 56-2 - Generator Armature Shaft - 1956 Rambler Series
HZ 56-3 - Spark Plugs - V-8 Hornet Series
HZ 56-4 - Coil Polarity - 1956 Hornet 6 & Wasp Series
HZ 56-5 - Back-up Lights Incorrectly Wired - 1956 Models
HZ 56-6 - Ignition Coil Unit - Rambler & Hornet V-8
HZ 56-7 - Generator Volt. Regulator - Rambler with OD
HZ 56-8 - Clock Noise in Radio - 1956 Rambler
HZ 56-9 - Radio Panelescent Dial Light - 1956 Rambler
HZ 56-10 - Distributor Assy. - 1956 80 Series
HZ 56-11 - Inst. Panel Cluster Remove. - 1956 Rambler
HZ 56-14 - Dist. Changes in ID & Specs - 80 Series

Group 4.000 - Fuel - Carburetion - Exhaust

HZ 56-1 - Starting & Cold Weather Warm up - 80 Series
HZ 56-2 - 1956 Rambler Carb. Specs AS-2349-S
HZ 56-4 - Rough Engine Idle, Wipers Operating - Rambler
HZ 56-5 - Carb. Flooding - Rambler AS-2349-S Carburetor
HZ 56-6 - Carb. Fuel Economy - Rambler AS-2349-S Carburetor
HZ 56-10 - Intake Manifold - 1955-56 80 Series

1955-56 80 Series Group 6.000 - Transmission

HZ 56-1 - Ultramatic Trans Throttle Valve
HZ 56-2 - Front Pump Kits - Ultramatic Transmission

Group 6.000 (Cont'd)

HZ 56-3 - Hydra-Matic Trans.
HZ 56-9 - T. V. Linkage Rod Measure. & Adjustment
HZ 56-10 - Slipping in Reverse - Flashaway
HZ 56-11 - Oil Leaks & Torus Drainback - Flashaway
HZ 56-12 - Flashaway Hydramatic Transmission
HZ 56-13 - Rear Brg. Retainer Oil Seal - Hydramatic
HZ 56-14 - Rear Brg. Snap Ring Fail - Stand. Transmission
HZ 56-20 - Modified 5610 Series Trans. Shift Pattern
HZ 56-21 - Automatic Transmission Fluids
HZ 56-22 - Scraping Noise in Reverse - 1956 Flashaway Transmission

Group 8.000 - Brakes & Wheels - Hub & Drum

HZ 56-1 - Hydrovac Power Brake Unit
HZ 56-3 - Clutch & Brake Pedal Shaft Lube. Fitting

Group 9.000 - Rear Axle - Propeller Shaft

HZ 56-1 - Rear Axle Pinion Seal - 51-55 Rambler Series
HZ 56-4 - Rear Axle Pinion Cone Setting

Group 10.000 - Front Axle - Front Suspension - Steering Gear

HZ 56-1 - Toe-In Adjustment
HZ 56-2 - Steer Gear Filler Plug
HZ 56-3 - Damaged Front Tires - Mod. 80

Group 11.000 - Frame Springs - Shock Absorber -Mud Pans

HZ 56-1 - Upper & Lower Shock Mounting
HZ 56-2 - Rear Shock Absorber Noise
HZ 56-3 - Rear Shock Absorbers
HZ 56-4 - Front Shock Lower Anchor Bolt

Group 13.000 - Weather Eye, Speedometer, Instrument Panel

HZ 56-1 - Weather Eye Install. Instructions
HZ 56-2 - Weather Eye Circ. w/o AC
HZ 56-4 - Speedometer Noise - 1956 Rambler
HZ 56-5 - Install. Inst. Weather Eye Form 1-477
HZ 56-6 - Belt Misalignment - Idler Pulley

1957 AMC-Hudson Bulletins

Groups 1.000 thru 13.000

1957 - Body Section

Z-D 57-11 - 3-7-57 - Outside Door Handles Binding
Z-D 57-13 - 3-18-57 - Door Lock Springs - 1957 Series

1957 - Group 1.000 - Engine

Z-D 57-6 Crankshaft Pulley Hub Oil Seal - 1957

Group 3.000 - Electrical

Z-D 57-5 - 3-18-57 - Headlight Dimmer Switch Cover
Drain - All Models
Z-D 57-6 - Rubber Coupling - Speedometer Drive Cable
Assy

1957 - Group 4.000 - Fuel - Carb. - Exhaust

Z-D 57-4 - Exh. Pipe Alignment - 1957 80 Series
Z-D 57-5 - Fast Idle Adjustments - WCFB-2593S & SA -
1957 80 Series
Z-D 57-7 - Rough Eng. Idle - Carter WCFB 4-bbl Carbs.

1957 - Group 5.000 - Clutch

Z-D 57-1 - Clutch Cover Removal - 80 Series 1957 - Group

6.000 - Transmission

Z 52-2 - D 57-1 - Torus Cover and Flywheel Assy's -
1956-1957
Z 57-3 - D 57-2 - Torus Drainback - 1956-1957
Hydramatic
Z-D 57-10 - 1-28-57 - Hydra-matic or OD Trans Remove -
80 Series
Z-D 57-11 - 2-22-57 - Hydra-matic Diagnosis Guide
Z-D 57-12 - 1957 80 Series. Trans. Shift Points
Z-D 57-14 - Bellcrank to Trans. Throttle Rod - 1957 Auto.
Trans
Z-D 57-15 - Manual Valve Body & Spacer - 1957
Auto. Trans
Z-D 57-21 - Rear Unit End Play - Auto Trans. All Series.
Z-D 57-22 - Hydra-matic Transmission Case
Z-D 57-23 - Torus Cover Leak - Hydramatic Trans.

Group 6.000 Cont'd.

Z-D 57-25 - Trans. Shift Lever Bushing - Stand. and
OD Trans
Z-D 57-3 - 12-11-57 - Oil Leaks 1956-1957 Hydramatic
Trans.
Z-D 57-5 - 1-7-57 - 3-4 Ball Check & Spring - 1957
HydraMatic Transmission
Z-D 57-6 - 1-8-57 - Replacing Hydramatic Trans. - 1956-
1957 Series
Z-D 57-8 - 1-24-57 - Direct Clutch Failure - V-8 Ultramatic
Z-D 57-9 - 1-28-57 - Rear Clutch Hub & Backing Plate -
1956-1957 Hydra-matic Transmission

1957 - Group 8.000 - Brakes & Wheels - Hub & Drum

Z-D 57-1 - Parking Brake Operation - 5700 Series.

1957 - Group 9.000 - Rear Axle - Propellor Shaft

Z-D 57-1 - Universal Joint Spider Repair Kit - 1949-56 10 &
40 Series
Z-D 57-3 - Propeller Shaft Flange Nut - 20 & 80 Series.

1957 - Group 10.000 - Front Axle - Front Suspension - Steering Gear

Z-D 57-10 - 4-19-57 - Front Suspension Lower Ctrl - 1957
Series
Z-D 57-2 - 12-5-56 - Steering Gear Stop Screws - 1957 80
Series
Z-D 57-3 - 12-14-57 - Power Steering Noise - 1957 20 &
80 Series
Z-D 57-3 - Power Steering Noise - 1957 20 & 80 Series.
Z-D 57-4 - 12-26-56 - Steering Wheel Position - 1957 80 Series
Z-D 57-7 - 3-27-57 - Power Cyl. Sill Brace Rod - 1957
80 Series
Z-D 57-8 - 4-23-57 - Steering Linkage Tube Clamp Adj.
5700 Series
Z-D 57-9 - 4-24-57 - Front Suspension Lower Control Arm -
1957 Series

1957 - Group 13.000 - Weather Eye - Speedometer - Instrument Panel

Z-D 57-4 - Weather Eye - 1957 80 Series

Hudson Technical Information Bulletins

Technical Information Bulletins - Volume I

TS 77-1 1948-1954 Dual Headlight Relay
TS 77-2 Exhaust Manifold Damper
TS 77-4 1948-1954 Cylinder Head Temperature Indicator Elements
TS 77-7 Hudson Double Safe Hydraulic Brakes
TS 77-9 Proper Clutch Flushing and Lubrication
TS 77-11 Aluminum Cylinder Heads
TS 77-14 1932 Essex-Terraplane Service Hints
TS 77-15 1948-1956 Six Cylinder Head Gasket
TS 77-16 1948-1954 All Hudson Heater Core and Hose Connections
TS 77-17 1940-1957 Hudson Spark Plug Recommendations
TS 77-18 1955-1956 Eng. Coding for Bore and Main and Connecting Rod Bearings
TS 77-19 1928 Hudson Information Models "O" and "S"
TS 77-20 1946-1954 Fuel and Temperature Dash Units
TS 77-21 1950-1954 Hudson Exterior Body Lacquers & Codes
TS 77-22 1948-1954 Front Seat Position All Models (except Jet)
TS 77-23 1948-1949 Hudson Body Lacquers & Codes

TS 78-1 1948-1954 All Models - Check Perimeter Frame
TS 78-2 1948-1954 Center Steering Pivot Pin Replacement
TS 78-3 1948-1954 Valve Adjustment
TS 78-4 1950-1954 Exterior Body Lacquers & Code - 1950-1954
TS 78-6 1940-1942 Chassis Model Information
TS 78-7 1942-1954 Speedometer Lubrication
TS 78-8 1930 Hudson Trimming Specifications for 1930 Models
TS 78-9 1946-1947 Model Information
TS 78-10 1940-1954 Headlight Mounting Ring & Housing Interchangeability
TS 78-14 1948-1954 Model Information
TS 78-15 1939 Model Information
TS 78-17 1938 Model Information
TS 78-21 1948-1956 Engine Information, Six Cylinder (except "202")
TS 78-22 Essex - Installation of Hot Water Heater in Models with Thermo-syphon Cooling

TS 78-24 1948-1954 Rear Axle Identification and Usage
TS 78-25 Drive-Master Service Hints

TS 80-1 1924-1936 Hudson Built Cars, Year Models by Serial Number

TS 81-1 Check the Starter Solenoid
TS 81-3 Body Painting and Preparation
TS 81-4 1946-1954 - Model Year Production Numbers
TS 84-2 Rebuilding the Water Distribution Baffle - 3 x 5 Six Cylinder Engine

Technical Information Bulletins - Volume II

TS 94-01 - 1940-42 - General Chassis Data
TS 94-02 - 1927-1954 - Starter Data for Hudson Built Cars
TS 94-03 - Compression Checks Prior to Tune-up
TS 94-04 - 1953-1948 - Tune-up Data
TS 95-01 - 1924-32 - Essex Serial Numbers & General Chassis Data
TS 95-02 - 1946-56 - Capacity Data
TS 95-03 - 1953-1954 Jet; 1954 Hornet, Wasp - Instrument Panels
TS 95-04 - 1946-1947 Tire Options
TS 96-01 - 1953-54 Jet & Super Jet Carburetor Float Level
TS 96-02 - 1948-54 Cylinder Head Temp. Indicator Elements
TS 96-03 - 1948-50 Exhaust Pipe and Muffler Clearances

Volume II - Cont'd

TS 97-01 - 1946-47 - General Chassis Data Sheet
TS 97-02 - 1940-54 - Electrical Equipment
TS 97-03 - 1948-49 - Hudson shipping weights.
TS 97-04 - 1936-37 - General Chassis Data Sheet
TS 97-05 - 1930-34 - General Chassis Data Sheet

TS 98-01 - 1919-23 - Essex 4-cylinder General Chassis Data Sheet
TS 98-02 - 1933 Essex-Terraplane Options and Color Options
TS 98-03 - 1933 Hudson & E-T Wheel Options
TS 98-04 - 1929 Hudson Super 6 Standard Equipment
TS 98-05 - 1938 Wheels & Tires
TS 98-06 - 1952 Hudson Accessory List
TS 98-07 - 1939 Hudson Accessory List
TS 99-01 - 1930-38 Engine Starting Numbers
TS 99-02 - 1926 Hudson Oil Pump Adjustment

II. Hudson Service Bulletins

TSB 98-01 - 1-27-33 - Hudson & Essex Specs, for Licensing Purposes
TSB 98-02 - 4-27-33 - Essex Commercial Cars Specs. for Licensing Purposes
TSB 98-03- 1933 - Specs for licensing purposes (Aug. 21, 1933)
TSB 98-04 - 1929 Hudson & Essex models and price listing

TSB 99-01 - 3-10-34 - Price, Equip. & Color Folder Changes

III. Dealer Bulletins

W. F. Groom - 3-1-34 - Production Start Dates
W. F. Groom - 3-1-34 - Comp. Club Sedan, Model LLU
W. F. Groom - 3-1-34 - Convertible Coupe Colors
W. F. Groom - 4-29-34 - Price Changes Effective May 1, 1934

IV. Miscellaneous

1929 - Wal Shock Absorber Service
1932 - Heat Indicator and Oil Pressure Warning Signals
General Parts Policy (1930-39 Master Group Parts Book) - 1940 Bulletin Series

Technical Information Bulletins - Volume III

I. Hudson Tech Sheet Number

TS 00-001 - 1931- Essex Super Six - Standard Equipment
TS 00-002 - 1929 - Paint Suppliers for 1929 Models
TS 00-003 - 1921 Hudson Model "0" Delco Electrical System
TS 00-004 - 1936-1950 Generator Specifications
TS 00-005 - 1925 Essex American Bosch Electrical System
TS 00-006 - 1936-1950 Starter Specifications

TS 01-001 - 1930-1933 Valve Timing
TS 01-002 - 1930-1933 Ignition Timing
TS 01-003 - 1914-1916 Hudson Six-40, Six-54 and Super-6 Ignition Timing
TS 01-004 - 1940 Hudson Models, Prices and Color Options
TS 01-005 - 1933-1939 Hudson Commercial Car Body Specifications
TS 02-001 - 1951 Engine Specifications
TS 02-002 - 1926 Essex Electrical Data (American-Bosch)
TS 02-003 - 1931-1937 Maintenance Procedures
TS 04-001 - 1929 Hudson & Essex Paint Codes and Suppliers
TS 04-002 - 1951-1956 Hudson 6 Engine Parts Interchange
TS 04-003 - 1931-1932 Dual Contact Distributor Setting
TS 04-004 - 1928 Type 5-A Electrolock
TS 04-005 - 1929-1931 Type 8 and 9 Electrolock
TS 04-006 - 1932 Essex, 1932-1933 Hudson 8 Type 15-S Electrolock
TS 04-007 - 1933-1937 Hudson and Terraplane Type 15-S, 24-B Mitchellock Ign.Switches
TS 04-008 - 1932-1933 W1 Carburetors

Volume III - Cont'd

II. Service Letters

Ser. 1178 - 1929 Hudson and Essex Oil Pumps

Ser. 1090 - 1929 Electric Gasoline and Oil Gauge Service

Technical Information Bulletins - Volume IV

TS 30-001 - 1930 Hudson Models T & U - Paint Specifications

TS 33-001 - 1933 Hudson & Essex Tune-up Specification Chart

TS 34-001 - Lubrication Chart - 1934 Models

TS 34-002 - Cleaning The Bendix Starter Drive - All Years, All Models

TS 34-003 - Oil Level Measurement - 1934 Hudson & Terraplane

TS 35-001 - Electric Gasoline and Water Level Gauge

TS 35-002 - Hudson Shock Absorbers - 1935 Models

TS 36-001 - Tire Pressures - 1933-1936 Models

TS 36-002 - Clutch Pedal Adjustment - 1936 Hudson & Terraplane

TS 36-003 - Heat Indicator - 1936 Models

TS 36-004 - Lock - 1936 Hudson & Terraplane

TS 37-001 - Accessories for 1937 Hudson & Terraplane

TS 37-002 - 1934-1937 Lubrication Specifications

TS 38-001 - Heater Ground Wire Attachment - 1934-1938 Models

TS 38-002 - 1938 Models - Horn Adjustment

TS 39-001 - Valve Tappet Adjustment - 1939 Six & Country Club Models

TS 40-001 - Propeller Shafts - 1940 Models TS40-002- Clutch - 1940 Models

TS 40-003 - Transmission and Overdrive removal - 1940 Models

TS 40-004 - 1936-1952 Timing Gear Applications TS41-001- Transmission Gear Interchange - 1941 Models

TS 41-002 - Transmission & Overdrive Lubrication - 1941 Models

TS 41-003 - 1935-1941 Car Color List

TS 41-004 - Door Lock or Outside Handle Binding - 1941 Models

TS 41-005 - 1941 Hudson - Bore, Piston and Bearing Sizes

TS 41-006 - 1941 Hudson - Bore, Piston and Bearing Sizes

TS 42-001 - Exhaust System Changes & Application - 1942 Models

TS 46-001 - Front End Alignment Chart - 1927-1946 Models

TS 57-001 - 1948-1957 - Brake Lining & Clutch Facing Specifications

